



Release Notes



ADI Terminal 1.3.0 Release Notes

December 2011

www.aditime.com



1.3.0 Release Documentation

Contents

ADI Time Terminal 1.3.0	3
ADI Time Terminal 1.2.2	3
ADI Time Terminal 1.2.1	3
ADI Time Terminal 1.2.0	3
ADI Time Terminal 1.1.0	4
ADI Time Terminal 1.0.1	4



ADI Time Terminal 1.3.0

Key	Case #	Docs Summary	Models(s)
CLOCK-28		Implemented 1:1 biometric functionality. <i>Note:</i> Turn ON 'Allow Pin Entry' to require employees to enter their Clock ID # before scanning finger.	ADI-P400L ADI-P700L
CLOCK-270		Positions with no Time Clock Nbr were being displayed in Department Transfer list.	ALL
CLOCK-367		Sync Time was resetting back to default time after application restart.	ALL
CLOCK-368		'GMT+12 Auckland' time zone was selecting incorrect local time file.	ALL
CLOCK-306		Selecting a list item on the Modify Employee page caused "Max call stack size exceeded."	ADI-P700S ADI-P700X ADI-P700L

ADI Time Terminal 1.2.2

Key	Case #	Docs Summary	Models(s)
CLOCK-310		Terminal could lose network connectivity after auto-sync completes. <i>Note:</i> If clock is in this state, firmware upgrade via USB to latest will resolve without loss of data.	All

ADI Time Terminal 1.2.1

Key	Case #	Docs Summary	Models(s)
CLOCK-362		Incorrect image was being displayed on unlock pages. Image displayed was for the bar code model.	ADI-P400X ADI-P700X ADI-P400L ADI-P700L
CLOCK-364		Grammar correction on Sync pages. Replace "Department" with "Departments"	ALL

ADI Time Terminal 1.2.0

Key	Case #	Docs Summary	Models(s)
CLOCK-359		Removed unused soap log tables in terminal database to save on disk space.	ALL

CLOCK-348		Static network settings are not enabled after switching back and forth from DHCP several times.	ALL
CLOCK-344		Added additional diagnostic tools for customer support.	ALL
CLOCK-357	81586	adiPad biometric terminal occasionally displaying wrong name when punching. Raised Lumidigm tolerance setting.	ALL

ADI Time Terminal 1.1.0

Key	Case #	Docs Summary	Models(s)
CLOCK-329	81125, 81272	Memory leak would cause usability issues until clock restarts. i.e. Clock time appears frozen.	ALL
CLOCK-317		Implemented hardware watch dog.	ALL
CLOCK-323		Linux command line output visible when configuring network settings.	ALL
CLOCK-341		Added scheduled "Sync" settings feature. Sync time is configurable through Preferences.	ALL
CLOCK-152		Added an idle setting that loads Main page after a specified amount of time. Setting is configurable through Preferences.	ALL

ADI Time Terminal 1.0.1

Key	Case #	Docs Summary	Models(s)
CLOCK-305		Added PIC firmware upgrade capability. Bar code module should be able to upgrade as part as the clock firmware package.	ALL